

ZeroTri® Heavy-Duty Degreaser



FEATURES

- Instant degreasing action
- Rapidly evaporates, leaving no residue
- No chlorinated solvents
- Ideal for degreasing metals
- Safe to use on most surfaces
- Nonfood Compounds Program Listed Category Code:
 C1 Registration # 059845 (Aerosol), # 059846 (Bulk)
- Acceptable for use in Canadian Food Processing Establishments



APPLICATIONS

- Air Compressors
- Alternators
- Bearings
- Chains & Cable Connections
- Cranes
- Electric Motors
- Fork Lifts
- Gasoline Engines

is (IDENTIFICATION SYSTEM)















AVAILABLE PRODUCTS

Part No.	Net Contents	Container	Case Pack	Case Wt.
03520	15 wt. oz. (425 mL)	Aerosol	12	15 lbs.
03528	1 gal. (3.78 L)	Container	4	30 lbs.
03505	5 gal. (18.93 L)	Pail	1	36 lbs.
03555	55 gal. (208 L)	Drum	1	346 lbs.



ZeroTri® Heavy-Duty Degreaser

PROPERTIES

Appearance / physical state

Odor

Evaporation rate

Boiling point
Vapor pressure

VOC

Solubility (water)

Liquid

Ether-like. Fruity.

> 1 (BuAc = 1)

> 132.8 °F (> 56 °C

> 75 mm Hg @ 20°C

62.4% per State and

Federal Consumer Product Regulations

35 % w/w

Color

Flash point

Vapor density

Percent volatile

Heat of combustion

Flammability limits

Specific gravity

Clear, water-white

1.4 °F (-17.0 °C)TCC

~ 3 (air = 1)

100%

> 30 kJ/g

lower 1.2%

upper 12.8 %

0.74 - 0.76 @ 20°C

HANDLING

Pressurized container: Do not pierce or burn, even after use. Do not use if spray button is missing or defective. Do not spray on a naked flame or any other incandescent material. Do not smoke while using or until sprayed surface is thoroughly dry. Do not cut, weld, solder, drill, grind, or expose containers to heat, flame, sparks, or other sources of ignition. Do not re-use empty containers. Do not breathe gas. Avoid contact with skin. Avoid contact with eyes. Avoid prolonged exposure. Avoid contact with clothing. Use only in well-ventilated areas. Wear appropriate personal protective equipment. Observe good industrial hygiene practices. When using, do not eat, drink or smoke. Wash hands thoroughly after handling.

STORAGE

Store locked up. Pressurized container. Protect from sunlight and do not expose to temperatures exceeding 50°F/122°F. Do not puncture, incinerate or crush. Contents under pressure. Keep away from heat, sparks and open flame. Keep container tightly closed. Store in a cool, dry place out of direct sunlight. Store in a well-ventilated place. Keep in an area equipped with sprinklers. Store away from incompatible materials (see Section 10 of the SDS).

DIRECTIONS

Spray on parts and equipment. Wipe with an absorbent cloth. If equipment is still dirty or greasy, repeat procedure.

DISPOSAL INFORMATION

Waste must be disposed of in accordance with any and all applicable environmental control rules and/or regulations.

