



F-104° Solvent Degreaser



FEATURES

- No chlorinated solvents
- Minimal residue
- No rinsing
- Safe to use on most surfaces
- Controlled evaporation
- Heavy-duty degreaser with a 104°F (40°C) flash point



APPLICATIONS

- Air Compressors
- Aircraft Structures
- Bonding Prep
- Cables
- Chains
- Cowlings
- Cranes
- Forklifts
- Gasoline Engines
- Gears
- Landing Gear
- Machine Tool Cleanup
- Power Tools
- Terminals

iS (IDENTIFICATION SYSTEM)



AVAILABLE PRODUCTS

Part No.	Net Contents	Container	Case Pack	Case Wt.
04920	15 wt. oz. (425 g)	Aerosol	12	15 lbs.
04905	5 gal. (18.93 L)	Pail	1	40 lbs.
04955	55 gal. (208 L)	Drum	1	369 lbs.



F-104° Solvent Degreaser

PROPERTIES

Appearance/physical state	Liquid	Color	Clear, water white
Odor	Mild. Orange.	Flash point	104.0°F (40.0°C)
Vapor pressure	2 mm Hg@20°C	Heat of combustion	>30 kJ/g
Vapor density	4.8 - 5.3	Evaporation rate	0.2 (BuAc = 1)
Viscosity	<3 cSt@25°C	Specific gravity	0.77 - 0.79 @ 20°C
Flammability limit	lower 2.5% upper 12.8%	VOC	97.2% per US State and Federal Consumer Product Regulations

HANDLING

Pressurized container: Do not pierce or burn, even after use. Do not use if spray button is missing or defective. Do not spray on a naked flame or any other incandescent material. Do not smoke while using or until sprayed surface is thoroughly dry. Do not cut, weld, solder, drill, grind, or expose containers to heat, flame, sparks, or other sources of ignition. Do not re-use empty containers. Do not breathe gas. Avoid contact with skin. Avoid contact with eyes. Avoid prolonged exposure. Avoid contact with clothing. Use only in well-ventilated areas. Wear appropriate personal protective equipment. Observe good industrial hygiene practices. When using, do not eat, drink or smoke. Wash hands thoroughly after handling.

STORAGE

Store locked up. Pressurized container. Protect from sunlight and do not expose to temperatures exceeding 50°F/122°F. Do not puncture, incinerate or crush. Contents under pressure. Keep away from heat, sparks and open flame. Keep container tightly closed. Store in a cool, dry place out of direct sunlight. Store in a well-ventilated place. Keep in an area equipped with sprinklers. Store away from incompatible materials (see Section 10 of the SDS).

DIRECTIONS

Spray on parts and equipment. Wipe with an absorbent cloth. If equipment is still dirty or greasy, repeat procedure.

DISPOSAL INFORMATION

Waste must be disposed of in accordance with any and all applicable environmental control rules and/or regulations.



800.241.8334 | www.lpslabs.com

TDS04920 160906