
Fluke current clamps
For use with multimeters, portable oscilloscopes and power quality analyzers





## **AC/DC** current clamp specifications

	80i-110s	i410	i1010	i30	i30s	i310s
DC range	0.1 A to 100 A	1 A to 400 A	1 A to 1000 A	30 mA to 30 A	30 mA to 30 A	0.1 A to 450 A
AC range	0.1 A to 70 A	1 A to 400 A	1 A to 600 A	30 mA to 20 A rms	30 mA to 20 A rms	0.1 A to 300 A
Accuracy	0.1 Å to 10 Å; dc to 1 kHz: ± 3 % + 50 mÅ; up to 100 Å add 15 %; up to 20 kHz add 12 %	3.5 % + 0.5 A for dc or ac (45 to 400 Hz)	2 % + 0.5 Å for dc or ac (45 to 400 Hz)	± 1 % of reading, ± 2 mA	± 1 % of reading, ± 2 mA	30 A range: 1 % + 50 mA 300 A range: 1 % + 300 mA
Bandwidth (-3 dB)	100 kHZ	3 kHz	10 kHz	dc to 20 kHz (-0.5 dB)	dc to 100 kHz (-0.5 dB)	DC to 20 kHz
Zero error adjustment	Yes	Yes	Yes	Yes	Yes	Yes
Maximum conductor diameter	11.8 mm (0.46 in)	30 mm (1.18 in)	30 mm (1.18 in)	19 mm (0.75 in)	19 mm (0.75 in)	19 mm (0.75 in)
Maximum conductor size	1 AWG	750 MCM or 2-500 MCM	750 MCM or 2-500 MCM	250 MCM	250 MCM	250 MCM
Output levels	10 mV/A, 100 mV/A	1 mV/A	1 mV/A	100 mV/A	100 mV/A	1 mV/A, 10 mV/A
Output cable	1.6 meter with BNC termination	1.2 meter with shrouded banana plugs	1.2 meter with shrouded banana plugs	1.5 meter with shrouded dual banana plue	2 meter with BNC termination	2 meters with BNC termination and a BNC to safety shrouded banana adapter
Battery life	40 hours	60 hours	60 hours	30 hours	30 hours	30 hours
Warranty	One-year	One-year	One-year	One-year	One-year	One-year
Safety	CAT II 600 V; CAT III 300 V	CAT III 600 V	CAT III 600 V	CAT III 300 V	CAT III 300 V	CAT III 300 V

## AC/DC current clamp selection guide

Meter	80i-110s	i410	i1010	i30	i30s	i310s
114/115/116/117	0.1 A to 100 A dc/	1.4 A to 400 A dc/	1.4 A to 1000 A dc/	30 mA to 30 A dc/	30 mA to 30 A dc/	0.1 A to 450 A dc/
	0.1 A to 70 A ac*	6 A to 400 A ac	6 A to 600 A ac	60 mA to 20 A ac	60 mA to 20 A ac	0.6 A to 300 A ac
233	0.1 A to 100 A dc/	1.4 Å to 400 Å dc/	1.4 A to 1000 A dc/	30 mA to 30 A dc/	30 mÅ to 30 Å dc/	0.1 A to 450 A dc/
	0.1 A to 70 A ac*	6 Å to 400 Å ac	6 A to 600 A ac	60 mA to 20 A ac	60 mÅ to 20 Å ac	0.6 A to 300 A ac
2711	0.1 A to 100 A dc/	1 A to 400 A dc/	1 A to 1000 A dc/ 1 A to	30 mA to 30 A dc/	30 mA to 30 A dc/	0.1 A to 450 A dc/
	0.1 A to 70 A ac*	1 A to 400 A ac	600 A ac	30 mA to 20 A ac	30 mA to 20 A ac	0.1 A to 300 A ac
2811	0.1 A to 100 A dc/	1 A to 400 A dc/	1 A to 1000 A dc/ 6 A to	30 mA to 30 A dc/	30 mÅ to 30 Å dc/	0.1 A to 450 A dc/
	0.2 A to 70 A ac*	6 A to 400 A ac	600 A ac	60 mA to 20 A ac	60 mÅ to 20 Å ac	2 A to 300 A ac
77-IV	0.1 A to 100 A dc/	1 A to 400 A dc/	1 A to 1000 A dc/ 5 A to	30 mA to 30 A dc/	30 mA to 30 A dc/	0.1 A to 450 A dc/
	0.1 A to 70 A ac*	5 A to 400 A ac	600 A ac	40 mA to 20 A ac	40 mA to 20 A ac	0.4 A to 300 A ac
175/177/179	0.11 A to 100 A dc/ 0.3 A to 70 A ac*	1.6 Å to 400 Å dc/ 30 Å to 400 Å ac	1.6 Å to 1000 Å dc/ 30 Å to 600 Å ac	30 mA to 30 A dc/ 300 mA to 20 A ac	30 mA to 30 A dc/ 300 mA to 20 A ac	0.1 A to 450 A dc/ 3 A to 300 A ac
1577/1587 Insulation Meter	0.1 A to 100 A dc/ 0.3 A to 70 A ac*	1.2 Å to 400 Å dc/ 30 Å to 400 Å ac	1.2 Å to 1000 Å dc/ 30 Å to 600 Å ac	30 mA to 30 A dc/ 300 mA to 20 A ac	30 mA to 30 A dc/ 300 mA to 20 A ac	0.1 A to 450 A dc/ 3 A to 300 A ac
83V/88V	0.1 A to 100 A dc/	1 A to 400 A dc/	1 A to 1000 A dc/ 1 A to	30 mA to 30 A dc/	30 mÅ to 30 Å dc/	0.1 A to 450 A dc/
	0.1 A to 70 A ac*	1 A to 400 A ac	600 A ac	30 mA to 20 A ac	30 mÅ to 20 Å ac	0.1 A to 300 A ac
87V	0.1 A to 100 A dc/	1 Å to 400 Å dc/	1 A to 1000 A dc/ 20 A to	30 mA to 30 A dc/ 200 mA	30 mA to 30 A dc/ 200 mA	0.1 A to 450 A dc/
	0.2 A to 70 A ac*	20 Å to 400 Å ac	600 A ac	to 20 A ac	to 20 A ac	2 A to 300 A ac
287/289	0.1 A to 100 A dc/	1 A to 400 A dc/	1 A to 1000 A dc/	30 mA to 30 A dc/	30 mÅ to 30 Å dc/	0.1 A to 450 A dc/
	0.1 A to 70 A ac*	1 A to 400 A ac	1 A to 600 A ac	30 mA to 20 A ac	30 mÅ to 20 Å ac	0.1 A to 300 A ac
123/124 ScopeMeters	0.1 A to 100 A dc/ 0.25 A to 70 A ac	1 Å to 400 Å dc/ 25 Å to 400 Å ac**	1 A to 1000 A dc/ 25 A to 600 A ac**	30 mA to 30 A dc/ 250 mA to 20 A ac**	30 mA to 30 A dc/ 250 mA to 20 A ac	0.1 A to 450 A dc/ 2.5 A to 300 A ac
190 Series Scopemeters	0.1 A to 100 A dc/	1 A to 400 A dc/	1 A to 1000 A dc/	30 mA to 30 A dc/	30 mÅ to 30 Å dc/	0.1 A to 450 A dc/
	0.1 A to 70 A ac	5 A to 400 A ac**	5 A to 600 A ac**	50 mA to 20 A ac**	50 mÅ to 20 Å ac	0.5 A to 300 A ac
8808A	0.1 A to 100 A dc/	1 Å to 400 Å dc/	1 A to 1000 A dc/	30 mA to 30 A dc/	30 mÅ to 30 Å dc/	0.1 A to 450 A dc/
	0.1 A to 70 A ac*	2 Å to 400 Å ac	2 A to 600 A ac	30 mA to 20 A ac	30 mÅ to 20 Å ac	0.2 A to 300 A ac
8845A/8846A	0.1 A to 100 A dc/	1 A to 400 A dc/	1 A to 1000 A dc/	30 mA to 30 A dc/	30 mÅ to 30 Å dc/	0.1 Å to 450 Å dc/
	0.1 A to 70 A ac*	1 A to 400 A ac	1 A to 600 A ac	30 mA to 20 A ac	30 mÅ to 20 Å ac	0.1 Å to 300 Å ac
705/707	0.1 A to 100 A dc, No ac*	4 A to 400 A dc, No ac	4 A to 1000 A dc, No ac	40 mA to 30 A dc, No ac	40 mA to 30 A dc, No ac	0.4 A to 450 A dc, No ac
715	0.1 A to 100 A dc, No ac*	4 A to 400 A dc, No ac	4 A to 1000 A dc, No ac	40 mA to 30 A dc, No ac	40 mA to 30 A dc, No ac	0.1 A to 450 A dc, No ac
787/789 Process Meters	0.1 A to 100 A dc/	1 Å to 400 Å dc/	1 A to 1000 A dc/	30 mA to 30 A dc/ 200 mA	3 mÅ to 30 Å dc/	0.1 A to 450 A dc/
	0.2 A to 70 A ac*	20 Å to 400 Å ac	20 A to 600 A ac	to 20 A ac	200 mÅ to 20 Å ac	2 A to 300 A ac

<sup>\*</sup> Requires PM9081 Adapter

\*\* Requires PM9082/001 Adapter

\*\*\*Only for use with the 430 Series Power Quality Analyzers