

Brady BLS1255 Laminator



Laminates documents up to 12" wide!

► BLS1255 Laminating System

- Quickly mount PowerMark™ output to plastic or aluminum sign blanks...takes only seconds!
- Laminating Options:
 - Mount label to a rigid plastic or aluminum sign panel
 - Mount label behind a rigid, clear acrylic sign panel to add rigidity while protecting the graphics...polished look for office areas
 - Overlamine documents with a single or double-sided flexible, clear overlaminate

BLS1255 Laminating System

Description	Catalog Number
BLS1255 Laminating System	105038
BLS1255 Cleaning Kit	13619

BLS1255 Clear Overlaminates - 50' length

Size	Catalog Number	
10"	105039	Single-sided polyester overlaminate
12"	105040	Single-sided polyester overlaminate
12"	105041	Double-sided polyester overlaminate

► Sign blanks to mount output from PowerMark™ printer

Plastic - rounded corners and hole punched - sold 10/pkg

Size	White	Yellow	Orange
4.25" x 6.25"	13620	13621	13622
4.25" x 10.25"	106458		
7.63" x 10.38"	13623	13624	13625
7.25" x 18.25"	106457		
10.25" x 10.25"	106459		
10.25" x 14.25"	13626	13627	13628

Aluminum - rounded corners and hole punched - sold 10/pkg

Size	White	Yellow	Orange
4.25" x 6.25"	13629	13630	13631
4.25" x 10.25"	106461		
7.25" x 10.25"	13632	13633	13634
7.63" x 10.38"	106460		
10.25" x 10.25"	106462		
10.25" x 14.25"	13635	13636	13637

Clear acrylic panels with pressure sensitive adhesive* (sign panel and overlaminate in one step) - sold 10/pkg.

Size	Catalog Number
4" x 6"	13638
4.25" x 10.25"	106464
7.25" x 10"	13639
7.25" x 10.25"	106463
10" x 14"	13640
10.25" x 10.25"	106465

*Use to mount output behind a clear panel to add rigidity while protecting the graphics...polished finish for office areas.

No Heat!
No Electricity!
No Messy
Chemicals!

Mount PowerMark™ output to plastic or aluminum sign panels in 3 easy steps!



Step 1: Peel away the first 1 1/2" of liner from the back of PowerMark™ printer output. Apply to blank panel, aligning edge of label with edge of panel.



Step 2: Insert sign into laminator and rotate handle until first 1" of sign is "pinched".

Stop. Then grasp liner of sign and pull at the same time as you rotate handle rapidly advancing sign through the laminator.



Step 3: In less than 30 seconds you have a rigid sign ready to hang. Choose from aluminum, plastic or clear acrylic panel materials.



Use the BLS1255 laminator to mount your PowerMark™ output to a rigid plastic or aluminum panel...in seconds.