

Fluke 353/355 AC/DC True-rms Clamp Meters



Fluke 355

Versatile, professional, accurate

Confidently take reliable readings with the true-rms Fluke 355 and 353 Clamp Meters—the tools of choice for high current clamp-on amp meter measurements up to 2000 A.

- Reliably handle a wide range of high-current applications with 2000 A ac + dc true-rms, 1400 A ac, and 2000 A dc
- Large 58 mm (2.3 in) jaw
- Inrush current measurement
- High voltage measurement of 1000 V ac + dc true-rms, 600 V ac, and 1000 V dc (355 only)
- Resistance to 400 K Ω (355 only)
- Continuity beeper (355 only)
- Frequency measurement to 1 KHz
- Selectable low-pass filter mode
- Min/Max/Avg
- Large display with backlight

Ordering information on page 6.



Fluke 353

Recommended accessories

Fluke 355



TL175
TwistGuard™
Test Leads
See page 66



80TK
Thermocouple Module
See page 68



C345
Large Soft Case
See page 63



C1600
Gear Tool Box
See page 63

Specifications

	General purpose				Industrial electrical		HVAC/R	High-end industrial, utility		iFlex accessory	Leakage
	365	373	374	375	376	381	902	353	355	i2500-10/ i2500-18	360
Measurements											
AC current	•	•	•	•	•	•	•	•	•	•	•
AC voltage	•	•	•	•	•	•	•	•	•	•	•
Resistance	•	•	•	•	•	•	•	•	•	•	•
Continuity	•	•	•	•	•	•	•	•	•	•	•
DC volts	•	•	•	•	•	•	•	•	•	•	•
DC current	•	•	•	•	•	•	•	•	•	•	•
True-rms	•	•	•	•	•	•	•	•	•	•	•
Frequency				•	•	•	•	•	•	•	•
AC + DC voltage									•		
AC + DC current								•	•		
Min/Max/Avg			•	•	•	•	•	•	•	•	•
Temperature							•				
Capacitance		•	•	•	•	•	•				
Special features											
Inrush current mode			•	•	•	•		•	•	•	
Low-pass filter				•	•	•					
18 inch iFlex Flexible Current Probe			Optional	Optional	Included	Included					
10 inch iFlex Flexible Current Probe			Optional	Optional	Optional	Optional					
Remote display						•					
Flashlight/torch	•										•
Display											
Display hold	•	•	•	•	•	•	•	•	•	•	•
Backlight	•	•	•	•	•	•	•	•	•	•	•
Specifications											
Jaw opening	0.7 in	1.3 in	1.3 in				1.2 in	2.3 in		5.7 in/3.2 in	1.5 in
Max wire size	17 mm (0.67 in)	750 MCM					750 MCM or three 500 MCM				1250 MCM
Current range ac rms	0 to 200.0 A	0 to 600.0 A			0 to 999.9 A		0 to 600.0 A	0 to 1400 A		0 to 2500 A	0 to 60 A
Accuracy ac current (50/60 Hz)	2 % \pm 5 counts						1.5 % \pm 5 counts		3 % \pm 5 counts	1 % \pm 5 counts	
AC response	True-rms										
Current range dc	0 to 200 A	0 to 600.0 A			0 to 999.9 A		0 to 200 μ A	0 to 2000 A			
Accuracy dc current	2 % \pm 5 counts	2 % \pm 5 counts				1 % \pm 5 counts		1.5 % \pm 5 counts			
Voltage range ac	0 to 600.0 V		0 to 1000 V			600.0 V		0 to 600.0 V			
Accuracy ac voltage	2 % \pm 5 counts	1 % \pm 5 counts	1.5 % \pm 5 counts			1 % \pm 5 counts		1 % \pm 5 counts			
Voltage range dc	0 to 600.0 V		0 to 1000 V			0 to 600.0 V		0 to 1000 V			
Accuracy dc voltage	2 % \pm 5 counts	1 % \pm 5 counts					1 % \pm 5 counts				
Resistance range	0 to 6000 Ω				0 to 60 k Ω		0 to 9999 Ω	0 to 400 K Ω			
Frequency measurement range	500 Hz					500 Hz		5 to 1000 Hz		500 Hz	

Fluke cases and holsters

A premium meter deserves a premium case



Soft cases

CAMO-C25 Camouflage Carrying Case

- High quality 1000D fabric
- Dimensions (HxWxD): 20.3 x 12.1 x 4.6 cm (8 x 4.8 x 1.8 in)

CAMO-C37 Camouflage Carrying Case

- High quality 1000D fabric
- Dimensions (HxWxD): 26.5 x 9 x 3 cm (10.5 x 3.5 x 1.2 in)

C12A Meter Case

- Case with inside pockets and belt loop
- Dimensions (HxWxD): 172 x 128 x 38 mm (6.8 x 5 x 1.5 in)

C75 Accessory Case

- Zippered carrying case
- Dimensions (HxWxD): 179 x 103 x 26 mm (7 x 4 x 1 in)

C50 Meter Case

- Case with inside pocket, belt loop and inside meter strap
- Dimensions (HxWxD): 192 x 90 x 38 mm (7.56 x 3.5 x 1.5 in)

C25 Large Soft Case for DMMs

- Case with padding and inside pocket
- Dimensions (HxWxD): 218 x 128 x 64 mm (8.6 x 5 x 2.52 in)

C90 Soft Case for DMMs

- Case with inside pocket and belt loop
- Dimensions (HxWxD): 205 x 90 x 72 mm (8 x 3.5 x 2.8 in)

C35 Soft Carrying Case

- Made of durable polyester 600D
- Dimensions (HxWxD): 220 x 140 x 65 mm (8.7 x 5.5 x 2.6 in)

C23 Soft Carrying Case

- Case with inside pocket and belt loop
- Dimensions (HxWxD): 225 x 95 x 58 mm (8.9 x 3.75 x 2.3 in)

C280 Soft Case

- Made of durable polyester 600D
- Dimensions (HxWxD): 230 x 185 x 65 mm (9 x 7.3 x 2.6 in)

C115 Soft Carrying Case

- Made of durable polyester 600D
- Dimensions (HxWxD): 240 x 205 x 75 mm (9.5 x 8 x 3 in)

C116 Soft Carrying Case

- Made of durable polyester 600D
- Dimensions (HxWxD): 240 x 230 x 65 mm (9.5 x 9 x 2.6 in)

C781 Meter Case

- Made of durable polyester 600D
- Dimensions (HxWxD): 269 x 141 x 90 mm (10.6 x 5.6 x 3.5 in)

C33 Soft Carrying Case

- Case with inside pocket and belt loop
- Dimensions (HxWxD): 280 x 115 x 55 mm (11 x 4.5 x 2.2 in)

C789 Meter and Accessory Case

- Made of durable polyester 600D
- Dimensions (HxWxD): 308 x 256 x 77 mm (12 x 10 x 3 in)

C43 Soft Carrying Case

- Made of durable polyester 600D
- Dimensions (HxWxD): 318 x 230 x 90 mm (12.5 x 9.1 x 3.5 in)

C550 Tool Bag

- Made of ballistic cloth with heavy-duty hardware
- Dimensions (HxWxD): 333 x 513 x 231 mm (13 x 20.2 x 9.1 in)

C345 Soft Case

- Made of durable polyester 600D
- Dimensions (HxWxD): 360 x 200 x 240 mm (14 x 8 x 9.5 in)

Hard cases

CXT Series Extreme Cases

- Models CXT80, CXT170, and CXT280 for various meter compatibility
- Unbreakable, watertight, airtight, chemical resistant and corrosion proof

C800 Meter and Accessory Case

- Dimensions (HxWxD): 230 x 385 x 115 mm (9 x 15 x 4.5 in)

C101 Hard Case

- Dimensions (HxWxD): 305 x 360 x 105 mm (12 x 14.2 x 4.1 in)

C100 Universal Carrying Case

- Dimensions (HxWxD): 397 x 346 x 122 mm (15.7 x 13.6 x 4.8 in)

C1600 Gear Box

- Includes five hook and loop straps to wrap cords and test leads
- Dimensions (HxWxD): 260 x 390 x 200 mm (10 x 15 x 7.8 in)

Leather cases

C520A Leather Tester Case

- Dimensions (HxWxD): 256 x 154 x 106 mm (10 x 6 x 4 in)

C510 Leather Meter Case

- Dimensions (HxWxD): 287 x 179 x 106 mm (11 x 7 x 4 in)

Holsters

H80M Protective Holster

- Includes a hanging magnet, general purpose hanger, and hook and loop straps
- Dimensions (HxWxD): 190 x 95 x 43 mm (7.5 x 3.7 x 1.7 in)

H5 Electrical Tester Holster

- Dimensions (HxWxD): 192 x 90 x 38 mm (7.5 x 3.5 x 1.5 in)

H3 Clamp Meter Holster

- Dimensions (HxWxD): 231 x 90 x 64 mm (9 x 3.5 x 2.5 in)

H6 IR Thermometer Holster

- Dimensions (HxWxD): 302 x 178 x 57 mm (11.9 x 7 x 2 in)

Cases and Holsters Selection Guide	113/114/115/116/117	27 II/28 II	77-4/115/117/119	83V/87V	233	287/289	8845A/8846A/8808A	120/190/22X Series	51-II/52-II/53-II B/54-II B	561/566/568	63/66/68	321/322	355	365/373/902	374/375/376/381	705/707	712/714/715/716/717/72X Series	718/719	753/754	787/789	T+/T+PRO	T5-600/T5-1000	1503/1507/1577
C12A	*																						
C23	*	*	*	*	*							*											
CAMO-C25	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C25	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C33	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C35	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
CAMO-C37	*	*	*	*	*	*	*	*	*	*	*	*	*	365	*	*	*	*	*	*	*	*	*
C43	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C50	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C75	The C75 is designed to hold test leads, probes, clips and other required accessories																						
C90	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C100	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	71X	*	*	787	*	*	*
C101	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C115/C116	*	*	*	*	*	*	*	*	*	*	*	*	*	365	*	*	*	*	*	*	*	*	*
C125	*	*	*	83V	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C280	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C345	The perfect case for carrying a wide range of Fluke handheld test tools and accessories																						
C510	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	787	*	*	*
C520A	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C550/C1600	The C550 and C1600 are large enough to hold accessories and multiple test tools																						
C781	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	72X	*	*	789	*	*	*
C789	*	*	*	*	*	*	*	*	*	*	*	*	*	365	*	*	*	*	*	*	*	*	*
C799	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
C800	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	71X	*	*	787	*	*	*
CXT80	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	72X	*	*	*	*	*	*
CXT170	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	71X	*	*	*	*	*	*
CXT280	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*