<u>Home</u> > <u>Products</u> > <u>Accessories</u> > <u>Other Accessories</u> > <u>2627-H</u> > Printer-friendly PDF

2627-H

Spare Sensor Kit with High-Accuracy Sensor

Highlights

One of the potential advantages of a digital thermo-hygrometer is that instead of sending the entire unit out for calibration, you can simply swap sensors and send only the sensors due for calibration out of the lab. The 1620A "DewK" Thermo-Hygrometer allows you to swap sensors without shutting it down or discontinuing your other readings.

Smart sensors make this possible because all of the calibration information is contained inside the sensor. Your costs are reduced because the 1620A never needs to be calibrated since it is only a display. Spare sensors like the 2627-H are less expensive to store, ship and recalibrate than an extra chart recorder.

With each kit you get a:

- · High-accuracy sensor
- Sensor case
- Sensor wall mount bracket
- 7.6 m (25 ft) extension cable

Models and Accessories





©1995-2015 Fluke Corporation

Source URL: http://us.flukecal.com/products/accessories/other-accessories/2627-h