




Integral Shank Drill Chucks

NST/NMTB-QC Taper

- Draw bar threads:
40 5/8" - 11



Type 7657

Taper Size K	Part Number	Chuck Capacity d1	D	G	L1	Wt lbs	Wrench Part Number
40	7-048-420Q	1/32 - 1/2	2	5/8 - 11	3.46	4.4	7-188-932K
	7-048-430Q	1/8 - 5/8	2-1/4		3.90	5.3	

Precision Drill Chuck Arbors


NST/NMTB-QC to Jacobs Taper

- Draw bar threads: 30 1/2" - 13
40 5/8" - 11
50 1" - 8



Type 5370

Taper Size K	Part Number	Chuck Mount K1	A	Wt lbs
30	7-052-031Q	JT1	.47	1.3
	7-052-033Q	JT3		
	7-052-0333Q	JT33		
	7-052-036Q	JT6		
40	7-052-041Q	JT1	.55	2.2
	7-052-042Q	JT2		
	7-052-043Q	JT3		
	7-052-0433Q	JT33		
	7-052-046Q	JT6		
50	7-052-053Q	JT3	.71	5.9
	7-052-0533Q	JT33		
	7-052-054Q	JT4		
	7-052-055Q	JT5		
	7-052-056Q	JT6		



R8 to Jacobs Taper

- Draw bar threads: 7/16" - 20

Type 5355

Taper Size K	Part Number	Chuck Mount K1	L	I	Wt lbs
R8	7-052-801	JT1	5	0.27	0.87
	7-052-802	JT2	5.18	0.25	0.90
	7-052-803	JT3	5.57	0.30	1.04
	7-052-806	JT6	5.27	0.22	1.03
	7-052-833	JT33	5.35	0.30	0.94

