



Main

| | |
|----------------------|--------------------------|
| Product | Combination Starter |
| Type | S |
| Control Circuit Type | Separate control circuit |

Complementary

| | |
|-------------------------|--|
| Control Circuit Voltage | 110 V AC 50 Hz 120 V AC 60 Hz |
| Starter Type | Non reversing |
| Number of Poles | 3P |
| Horsepower Rating | 100 hp 460 V AC 3 phases 100 hp 575 V AC 3 phases |
| System Voltage | 600 V AC |
| Control Units | No control units |
| Pilot Light | No indicator |
| Auxiliary Contacts | Without |
| Thermal overload type | Melting alloy 3 Thermal Units |
| Disconnect Type | Fusible disconnect switch, Type H Fuse, 200 A |
| NEMA size | 4 |

Environment

| | |
|----------------|--|
| Enclosure Type | NEMA 1 painted sheet steel and with external reset |
|----------------|--|

Offer Sustainability

| | |
|------------------------|--|
| RoHS (date code: YYWW) | Will not be compliant Will not be compliant |
|------------------------|--|

Contractual warranty

| | |
|-----------------|-----------|
| Warranty period | 18 months |
|-----------------|-----------|